

Dolan Chemical Laboratory 4001 Bixby Road Groveport, OH 43125 T: 614-836-4221, Audinet 210-4221 F: 614-836-4168, Audinet 210-4168 http://aepenv/labs

Water Analysis

Location: Mountaineer Plant Report Date: 9/20/2012

1	St	St	ar	ı	F۵	ed	

Sample Number:	123935-001	Date Co	llected:	09/12/2012	2 08:00	Date Received: 9/1	2/2012
Parameter		Result Units	RL	MDL	Analysis By	Analysis Date/Time	Method
Selenium, Se		851 ua/l	0.5	0.1	DPC	09/17/2012 11:48	FPA 200.8

2nd	Stage	Feed
-----	-------	------

Sample Number:	123935-002		Date Co	llected:	09/12/2012 08:00		Date Received: 9/12/2012	
Parameter		Result	Units	RL	MDL	Analysis By	Analysis Date/Time	Method
Selenium, Se		10.1	ug/L	0.5	0.1	DPC	09/17/2012 11:53	EPA 200.8

Bioreactor Effluent

Bioreactor Effluent										
Sample Number: 123935-003			Date Collec	cted:	09/12/2012	08:00	Date Received: 9/12/2012			
Parameter		Result	Units	RL	MDL	Analysis By	Analysis Date/Time	Method		
Selenium, Se		0.9	ug/L	0.5	0.1	DPC	09/17/2012 11:58	EPA 200.8		

Brian Snyder, Chemist II

Email bssnyder@aep.com Tel. 614-836-4224

Fax 614-836-4168 Audinet 210-4224

THIS TEST REPORT RELATES ONLY TO THE ITEMS TESTED AND SHALL NOT BE REPRODUCED EXCEPT IN FULL WITHOUT WRITTEN APPROVAL OF THE LABORATORY. ALL TEST RESULTS MEET ALL OF THE REQUIREMENTS OF THE ACCREDITING AUTHORITY, UNLESS OTHERWISE NOTED.